



2715 Reynolda Road, Winston-Salem, NC 27106 USA  
 Phone 1-336-722-1616 • Fax 1-336- 722-1655  
 Admin@SkyQuestInternational.com • www.SkyQuestInternational.com

## Aircraft Specifications



### ENGINES

Engine Type and Model	:	Rolls Royce Dart 532-7	
Operator Approved Engine TBO	:	6,400 Hours	
		<b>Left Engine</b>	<b>Right Engine</b>
Serial Number	:	16002	14012
Hours Since New	:	13,166	24,565
Hours Since Overhaul	:	3,051	1,291
Cycles Since Overhaul	:	4,540	2,604
Hours Since HSI	:	1,417	1,259

### PROPELLERS

Propeller Type & Model	:	Dowty Rotol R193/4-30-4/50	
Operator Approved Propeller TBO	:	4,000	
		<b>Left Propeller</b>	<b>Right Propeller</b>
Serial Number	:	193/59/79	DRG/364/66
Hours Since Overhaul	:	1,756	2,555

### LANDING GEAR

<u>Description</u>	<u>NLG</u>	<u>MLG LH</u>	<u>MLG RH</u>
Part Number	200077005	200042.006	200042.016
Serial Number	CPACC32/58	G14/65/86R	OC.010.86R
C. S. O.	4,809	9,662	9,662
C. B. O.	10,000	10,000	10,000
Remaining	5,191	338	338

## MAINTENANCE

DESCRIPTION	DATE	TSN OF A/C	INTERVAL	REMAIN
MID OP INSPECTION	06/03/2006	32,765:02	215:00	69:34
MAINTENANCE VISIT 1	21/07/2004	31,975:48	3200:00	2,265:20
MAINTENANCE VISIT 2	16/02/2005	32,286:30	3200:00	2,576:02
MAINTENANCE VISIT 3	17/08/2005	32,558:55	3200:00	2,848:27

## AVIONICS

<u>Component</u>	<u>Manufacturer/Model</u>
VHF Com (dual)	Collins
VHF Nav (dual)	Collins
ADF	Collins/51Y-7A
DME	Collins/DME-40
HF Transceiver	Collins/671U-4A
VHF Transceiver	Collins/313N-5A
Emergency Locator	DM-ELT6.1
VOR Locator	Collins/51R-8A
Glidescope	Collins/512-4
ADF	Collins/51Y-7A
GPS	TNL/200A
APU Solar 1	62T-25
ATC	King
Radio Altimeter	Collins DRI-55
Autopilot	Collins



## WEIGHTS

Maximum Take-off Weight	:	42,000	Lbs
Empty Operating Weight	:	27,964	Lbs
Fuel Capacity	:	2,368	Gals

## OTHER INFORMATION

New Paint January 2007  
Auxiliary Power Unit (APU)

SPECIFICATIONS ARE SUBJECT TO VERIFICATION UPON INSPECTION. THIS AIRCRAFT IS OFFERED SUBJECT TO PRIOR SALE OR LEASE AND MAY BE WITHDRAWN FROM THE MARKET WITHOUT PRIOR NOTICE.

*For further information regarding this aircraft please contact Greg or Jeff Melang at SkyQuest International, LLC. Phone 1-336-722-1616 Fax 1-336-722-1655  
Email: Admin@SkyQuestInternational.com Website: www.SkyQuestInternational.com*